

PW118B AP0040



Visit our website at www.aerovi.com

TSN	30,715.20
CSN	43,467
TSO	987.30
CSO	1,266
TSHSI	987.30

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1,266	25,000	1.000 / 1.380	17,189
HP Impeller	3072767-01	1,266	15,000	0.600 / 0.830	17,148
LP Disk	3036412	1,266	25,000	1.667 / 1.667	13,731
Front Cover	3039640	1,266	15,000	1.354 / 1.354	9,812
Rear Cover	3039639	1,266	15,000	1.000 / 1.000	13,734
Inter Stage Seal	3039172	1,266	15,000	1.000 / 1.000	13,734
HP Disk	3041511	1,266	15,000	1.000 / 1.000	13,734
PT1 Disk	3038613	1,266	30,000	1.000 / 1.000	28,734
PT2 Disk	3033914	1,266	30,000	1.000 / 1.000	28,734
HP Blades	3115601-01	1,266	15,000	1.000 / 1.000	13,734

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President – Aircraft & Engines
pgibson@aerovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director - Engine Services
pw.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Director Regional, América Latina
gmr.sales@aerovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Director of Regional Operations
nbaldock@aerovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director – Engine Services
Rg.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 891-3268