

PW120A 121267			
RGB Module		TMM Module	

TSN:	39,907.40	TSN:	39,104
CSN:	40,401	CSN:	39,687
TSO:	12,060.80	TSO:	12,060
CSO:	9,687	CSO:	9,687
TSHSI:	N/A	TSHSI:	1,359



Visit our website at [www.aerovi.com](http://www.aerovi.com)

### Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining
LP Impeller	3040689	15,922	25,000	9,078
HP Impeller	3043243	23,279	30,000	6,721
LP Disk	3036212	1,472	30,000	28,528
Front Cover	3049049-01	1,472	15,000	13,528
Rear Cover	3041486	1,472	15,000	13,528
Inter Stage Seal	3041474	1,472	15,000	13,528
HP Disk	3043243	1,472	15,000	13,528
PT1 Disk	3038613	21,677	30,000	8,323
PT2 Disk	3033914	21,677	30,000	8,323
HP Blades	3115301-01	1,472	15,000	13,528

**LEGEND:** TSN - Time Since New; CSN - Cycles Since New; TSO - Time Since Overhaul; CSO - Cycles Since Overhaul; TSHSI - Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

**Joel Johnson**  
Senior Director - Program Sales  
[jjohnson@aerovi.com](mailto:jjohnson@aerovi.com)  
(231) 288-7661

**Pamela Wilton**  
Director - Engine Services  
[pw.aesales@aerovi.com](mailto:pw.aesales@aerovi.com)  
(204) 233-1922

**Rory Guina**  
Director - Engine Services  
[rg.aesales@aerovi.com](mailto:rg.aesales@aerovi.com)  
(204) 891-3268

**Rylee Luker**  
Program Coordinator - Engine Sales  
[rluker@aerovi.com](mailto:rluker@aerovi.com)  
(231) 720-0792

**Steve McKee**  
Engine Sales  
[smckee@aerovi.com](mailto:smckee@aerovi.com)  
(231) 327-7886