

PW127F ESN: AM0059



Visit our website at www.aerovi.com

TSN	21,325.3
CSN	23,750
TSO	6,533.3
CSO	9,354
TSHSI	552.1

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3039487	9,354	15,000	5,646	5,646
HP Impeller	3043293	9,354	15,000	5,646	5,646
LP Disk	3039412	9,354	15,000	5,646	5,646
Front Cover	3039640	809	15,000	14,191	12,340
Rear Cover	3039639	9,354	15,000	5,646	5,646
Inter Stage Seal	3039172	6,618	15,000	8,382	6,705
HP Disk	3041511	9,354	15,000	5,646	5,646
PT1 Disk	3038513	23,750	30,000	6,250	6,250
PT2 Disk	3033914	23,750	30,000	6,250	6,250
HP Blades	3115601-01	9,354	15,000	5,646	5,646

- Fresh repair and test cell run by StandardAero, January 2017

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President
pgibson@erovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Sales Representative
Pw.aesales@erovi.com
Tel (231) 799-9000
Cell (204) 233-1922

NICK BALDOCK
Regional Director – Europe/ Middle
East/ Africa
nbaldock@erovi.com
Tel 011 44 1454 820082
Cell 011 44 7773 315567

RORY GUINA
Sales Representative
Rg.aesales@erovi.com
Tel (231) 799-9000
Cell (204) 891-3268