

PW118B ESN AA0014



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN	31,575.60
CSN	45,032
TSO	1,169.70
CSO	1,573
TSHSI	1,169.70

### Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1,573	25,000	1.000 / 1.380	16,962
HP Impeller	3072767-01	1,573	15,000	0.600 / 0.830	16,921
LP Disk	3036412	1,573	25,000	1.667 / 1.667	13,424
Front Cover	3039640	1,573	15,000	1.354 / 1.354	9,505
Rear Cover	3039639	1,573	15,000	1.000 / 1.000	13,427
Inter Stage Seal	3039172	1,573	15,000	1.000 / 1.000	13,427
HP Disk	3041511	1,573	15,000	1.000 / 1.000	13,427
PT1 Disk	3038613	1,573	30,000	1.000 / 1.000	28,427
PT2 Disk	3033914	1,573	30,000	1.000 / 1.000	28,427
HP Blades	3115601-01	1,573	15,000	1.000 / 1.000	13,427

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**PETE GIBSON**  
Vice President  
[pgibson@aerovi.com](mailto:pgibson@aerovi.com)  
Tel (231) 799-9000  
Cell (231) 215-4977

**PAMELA WILTON**  
Director Engine Services  
[Pw.aesales@aerovi.com](mailto:Pw.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 233-1922

**GERARDO MORALES**  
Regional Director – AL  
[gmr.sales@aerovi.com](mailto:gmr.sales@aerovi.com)  
Cell 52-1-442-545-7622

**NICK BALDOCK**  
Regional Director – Europe/ Middle  
East/ Africa  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
Tel 44 1454 820082  
Cell 44 7773 315567

**RORY GUINA**  
Director Engine Services  
[Rg.aesales@aerovi.com](mailto:Rg.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 891-3268