

PW118B ESN AA0016



Visit our website at www.aerovi.com

TSN	29,863.80
CSN	41,468
TSO	398.40
CSO	516
TSHSI	398.40

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	516	25,000	1.000 / 1.380	17,694
HP Impeller	3072767-01	516	15,000	0.600 / 0.830	17,737
LP Disk	3036412	516	25,000	1.667 / 1.667	14,481
Front Cover	3039640	516	15,000	1.000 / 1.000	10,562
Rear Cover	3039639	516	15,000	1.000 / 1.000	14,484
Inter Stage Seal	3039172	516	15,000	1.000 / 1.000	14,484
HP Disk	3041511	516	15,000	1.000 / 1.000	14,484
PT1 Disk	3038613	11,498	30,000	1.000 / 1.000	18,502
PT2 Disk	3033914	11,498	30,000	1.000 / 1.000	18,502
HP Blades	3115601-01	516	15,000	1.000 / 1.000	14,484

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President
pgibson@aerovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director Engine Services
Pw.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Regional Director – AL
gmr.sales@aerovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Regional Director – Europe/ Middle
East/ Africa
nbaldock@aerovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director Engine Services
Rg.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 891-3268