

PW118B ESN AA0017



Visit our website at www.aerovi.com

TSN	31,823.20
CSN	45,515
TSO	1,167.60
CSO	1,671
TSHSI	1,671.60

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1,671	25,000	1.000 / 1.380	16,881
HP Impeller	3072767-01	1,671	15,000	0.600 / 0.830	16,840
LP Disk	3036412	1,671	25,000	1.667 / 1.667	13,326
Front Cover	3039640	1,671	15,000	1.354 / 1.354	9,407
Rear Cover	3039639	1,671	15,000	1.000 / 1.000	13,329
Inter Stage Seal	3039172	1,671	15,000	1.000 / 1.000	13,329
HP Disk	3041511	1,671	15,000	1.000 / 1.000	13,329
PT1 Disk	3038613	8,287	30,000	1.000 / 1.000	21,713
PT2 Disk	3033914	15,542	30,000	1.000 / 1.000	14,458
HP Blades	3115601-01	1,671	15,000	1.000 / 1.000	13,329

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President
pgibson@aerovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director Engine Services
Pw.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Regional Director – AL
gmr.sales@aerovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Regional Director – Europe/ Middle
East/ Africa
nbaldock@aerovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director Engine Services
Rg.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 891-3268