

# PW118B ESN AP0035



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN	31,765.00
CSN	42,265
TSO	889.00
CSO	1,324
TSHSI	889.00

## Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1,324	25,000	1.000 / 1.380	17,150
HP Impeller	3043294	1,324	15,000	0.600 / 0.830	17,108
LP Disk	3036412	1,324	25,000	1.667 / 1.667	13,673
Front Cover	3039640	1,324	15,000	1.354 / 1.354	9,754
Rear Cover	3039639	1,324	15,000	1.000 / 1.000	13,676
Inter Stage Seal	3039172	1,324	15,000	1.000 / 1.000	13,676
HP Disk	3041511	1,324	15,000	1.000 / 1.000	13,676
PT1 Disk	3038613	12,265	30,000	1.000 / 1.000	17,735
PT2 Disk	3033914	12,265	30,000	1.000 / 1.000	17,735
HP Blades	3115601-01	1,324	15,000	1.000 / 1.000	13,676

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**PETE GIBSON**  
Vice President  
[pgibson@aerovi.com](mailto:pgibson@aerovi.com)  
Tel (231) 799-9000  
Cell (231) 215-4977

**PAMELA WILTON**  
Director Engine Services  
[Pw.aesales@aerovi.com](mailto:Pw.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 233-1922

**GERARDO MORALES**  
Regional Director – AL  
[gmr.sales@aerovi.com](mailto:gmr.sales@aerovi.com)  
Cell 52-1-442-545-7622

**NICK BALDOCK**  
Regional Director – Europe/ Middle  
East/ Africa  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
Tel 44 1454 820082  
Cell 44 7773 315567

**RORY GUINA**  
Director Engine Services  
[Rg.aesales@aerovi.com](mailto:Rg.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 891-3268