

# PW118B ESN AP0036



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN	31,663.50
CSN	42,950
TSO	4.60
CSO	1
TSHSI	4.60

## Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1	25,000	1.000 / 1.380	18,115
HP Impeller	3072767-01	1	15,000	0.600 / 0.830	18,071
LP Disk	3036412	1	25,000	1.667 / 1.667	14,996
Front Cover	3039640	1	15,000	1.354 / 1.354	11,077
Rear Cover	3039639	1	15,000	1.000 / 1.000	14,999
Inter Stage Seal	3039172	1	15,000	1.000 / 1.000	14,999
HP Disk	3041511	1	15,000	1.000 / 1.000	14,999
PT1 Disk	3038613	1	30,000	1.000 / 1.000	29,999
PT2 Disk	3033914	1	30,000	1.000 / 1.000	29,999
HP Blades	3115601-01	1	15,000	1.000 / 1.000	14,999

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**PETE GIBSON**  
Vice President  
[pgibson@aerovi.com](mailto:pgibson@aerovi.com)  
Tel (231) 799-9000  
Cell (231) 215-4977

**PAMELA WILTON**  
Director Engine Services  
[Pw.aesales@aerovi.com](mailto:Pw.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 233-1922

**GERARDO MORALES**  
Regional Director – AL  
[gmr.sales@aerovi.com](mailto:gmr.sales@aerovi.com)  
Cell 52-1-442-545-7622

**NICK BALDOCK**  
Regional Director – Europe/ Middle East/ Africa  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
Tel 44 1454 820082  
Cell 44 7773 315567

**RORY GUINA**  
Director Engine Services  
[Rg.aesales@aerovi.com](mailto:Rg.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 891-3268