

PW118B ESN 115632



Visit our website at www.aerovi.com

TSN	43,510.80
CSN	56,726
TSO	1,176.00
CSO	1,764
TSHSI	1,176.00

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1,764	25,000	1.000 / 1.380	16,823
HP Impeller	3043294	1,764	15,000	0.600 / 0.830	16,782
LP Disk	3036412	1,764	25,000	1.667 / 1.667	13,233
Front Cover	3039640	1,764	15,000	1.354 / 1.354	9,314
Rear Cover	3039639	1,764	15,000	1.000 / 1.000	13,236
Inter Stage Seal	3039172	1,764	15,000	1.000 / 1.000	13,236
HP Disk	3041511	1,764	15,000	1.000 / 1.000	13,236
PT1 Disk	3038613	1,764	30,000	1.000 / 1.000	28,236
PT2 Disk	3033914	1,764	30,000	1.000 / 1.000	28,236
HP Blades	3115601-01	1,764	15,000	1.000 / 1.000	13,236

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President
pgibson@aerovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director Engine Services
Pw.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Regional Director – AL
gmr.sales@aerovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Regional Director – Europe/ Middle East/ Africa
nbaldock@aerovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director Engine Services
Rg.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 891-3268