

PW118B 115647



Visit our website at www.aerovi.com

TSN	42,370.9
CSN	58,838
TSO	14,854.0
CSO	19,774
TSHSI	6,267.2

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	19,774	25,000	1.000 / 1.380	3,681
HP Impeller	3043294	19,774	15,000	0.600 / 0.830	3,672
LP Disk	3036412	8,740	25,000	1.667 / 1.667	6,257
Front Cover	3039640	8,740	15,000	1.354 / 1.354	2,338
Rear Cover	3039639	8,740	15,000	1.000 / 1.000	6,260
Inter Stage Seal	3039172	8,740	15,000	1.000 / 1.000	6,260
HP Disk	3041511	8,740	15,000	1.000 / 1.000	6,260
PT1 Disk	3038613	8,740	30,000	1.000 / 1.000	21,260
PT2 Disk	3033914	8,740	30,000	1.000 / 1.000	21,260
HP Blades	3115601-01	8,740	15,000	1.000 / 1.000	6,260

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President – Aircraft & Engines
pgibson@aerovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director - Engine Services
pw.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Director Regional, América Latina
gmr.sales@aerovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Director of Regional Operations
nbaldock@aerovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director – Engine Services
Rg.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 891-3268