

PW118B 115550



Visit our website at www.aerovi.com

TSN	47,373.9
CSN	60,760
TSO	15,334.7
CSO	20,775
TSHSI	3,036.8

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	20,775	25,000	1.000 / 1.380	2,971
HP Impeller	3043294	20,775	15,000	0.600 / 0.830	2,963
LP Disk	3036412	9,714	25,000	1.667 / 1.667	5,283
Front Cover	3039640	4,318	15,000	1.354 / 1.354	6,760
Rear Cover	3039639	9,714	15,000	1.000 / 1.000	5,286
Inter Stage Seal	3039172	9,714	15,000	1.000 / 1.000	5,286
HP Disk	3041511	9,714	15,000	1.000 / 1.000	5,286
PT1 Disk	3038613	9,714	30,000	1.000 / 1.000	20,286
PT2 Disk	3033914	9,714	30,000	1.000 / 1.000	20,286
HP Blades	3115601-01	9,714	15,000	1.000 / 1.000	5,286

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President – Aircraft & Engines
pgibson@erovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director - Engine Services
pw.aesales@erovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Director Regional, América Latina
gmr.sales@erovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Director of Regional Operations
nbaldock@erovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director – Engine Services
Rg.aesales@erovi.com
Tel (231) 799-9000
Cell (204) 891-3268