

PW118B 115698



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN	37,023.9
CSN	51,607
TSO	8,218.8
CSO	11,057
TSHSI	1,169.7

### Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	11,057	25,000	1.000 / 1.380	10,063
HP Impeller	3043294	11,057	15,000	0.600 / 0.830	10,038
LP Disk	3036412	11,057	25,000	1.667 / 1.667	3,940
Front Cover	3039640	11,057	15,000	1.354 / 1.354	21
Rear Cover	3039639	11,057	15,000	1.000 / 1.000	3,943
Inter Stage Seal	3039172	11,057	15,000	1.000 / 1.000	3,943
HP Disk	3041511	11,057	15,000	1.000 / 1.000	3,943
PT1 Disk	3038613	20,013	30,000	1.000 / 1.000	7,987
PT2 Disk	3033914	11,057	30,000	1.000 / 1.000	18,943
HP Blades	3115601-01	11,057	15,000	1.000 / 1.000	3,943

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**PETE GIBSON**  
Vice President – Aircraft & Engines  
[pgibson@aerovi.com](mailto:pgibson@aerovi.com)  
Tel (231) 799-9000  
Cell (231) 215-4977

**PAMELA WILTON**  
Director - Engine Services  
[pw.aesales@aerovi.com](mailto:pw.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 233-1922

**GERARDO MORALES**  
Director Regional, América Latina  
[gmr.sales@aerovi.com](mailto:gmr.sales@aerovi.com)  
Cell 52-1-442-545-7622

**NICK BALDOCK**  
Director of Regional Operations  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
Tel 44 1454 820082  
Cell 44 7773 315567

**RORY GUINA**  
Director – Engine Services  
[Rg.aesales@aerovi.com](mailto:Rg.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 891-3268