

PW118B AA0026



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN	30,325.80
CSN	42,912
TSO	15,379.90
CSO	21,145
TSHSI	7,960

## Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	21,145	25,000	1.000 / 1.380	2,721
HP Impeller	3043294	21,145	15,000	0.600 / 0.830	2,714
LP Disk	3036412	10,755	25,000	1.667 / 1.667	4,242
Front Cover	3039640	10,755	15,000	1.354 / 1.354	323
Rear Cover	3039639	10,755	15,000	1.000 / 1.000	4,245
Inter Stage Seal	3039172	10,755	15,000	1.000 / 1.000	4,245
HP Disk	3041511	10,755	15,000	1.000 / 1.000	4,245
PT1 Disk	3038613	21,145	30,000	1.000 / 1.000	8,855
PT2 Disk	3033914	21,145	30,000	1.000 / 1.000	8,855
HP Blades	3115601-01	10,755	15,000	1.000 / 1.000	4,245

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**PETE GIBSON**  
Vice President – Aircraft & Engines  
[pgibson@aerovi.com](mailto:pgibson@aerovi.com)  
Tel (231) 799-9000  
Cell (231) 215-4977

**PAMELA WILTON**  
Director - Engine Services  
[pw.aesales@aerovi.com](mailto:pw.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 233-1922

**GERARDO MORALES**  
Director Regional, América Latina  
[gmr.sales@aerovi.com](mailto:gmr.sales@aerovi.com)  
Cell 52-1-442-545-7622

**NICK BALDOCK**  
Director of Regional Operations  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
Tel 44 1454 820082  
Cell 44 7773 315567

**RORY GUINA**  
Director – Engine Services  
[Rg.aesales@aerovi.com](mailto:Rg.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 891-3268