

PW118B AP0056



Visit our website at www.aerovi.com

TSN	30,382
CSN	43,039
TSO	15,412.8
CSO	21,434
TSHSI	7,797.8

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	21,434	25,000	1.000 / 1.380	2,512
HP Impeller	3043294	21,434	15,000	0.600 / 0.830	2,505
LP Disk	3036412	11,008	25,000	1.667 / 1.667	3,989
Front Cover	3039640	11,008	15,000	1.354 / 1.354	70
Rear Cover	3039639	11,008	15,000	1.000 / 1.000	3,992
Inter Stage Seal	3039172	11,008	15,000	1.000 / 1.000	3,992
HP Disk	3041511	11,008	15,000	1.000 / 1.000	3,992
PT1 Disk	3038613	21,434	30,000	1.000 / 1.000	8,566
PT2 Disk	3033914	21,434	30,000	1.000 / 1.000	8,566
HP Blades	3115601-01	11,008	15,000	1.000 / 1.000	3,992

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President – Aircraft & Engines
pgibson@aerovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director - Engine Services
pw.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Director Regional, América Latina
gmr.sales@aerovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Director of Regional Operations
nbaldock@aerovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director – Engine Services
Rg.aesales@aerovi.com
Tel (231) 799-9000
Cell (204) 891-3268