

# PW120A 121267



Visit our website at [www.aerovi.com](http://www.aerovi.com)

RGB Module		TMM Module	
TSN	39,907.40	TSN	39,104.20
CSN	40,401	CSN	39,687
TSO	12,060.80	TSO	12,060.08
CSO	9,687	CSO	9,687
TSHSI	N/A	TSHSI	1,358.90

## Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining
LP Impeller	3040689	15,922	25,000	9,078
HP Impeller	3043243	23,279	30,000	6,721
LP Disk	3036212	1,472	30,000	28,528
Front Cover	3049049-01	1,472	15,000	13,528
Rear Cover	3041486	1,472	15,000	13,528
Inter Stage Seal	3041474	1,472	15,000	13,528
HP Disk	3043243	1,472	15,000	13,528
PT1 Disk	3038613	21,677	30,000	8,323
PT2 Disk	3033914	21,677	30,000	8,323
HP Blades	3115301-01	1,472	15,000	13,528

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**PETE GIBSON**  
Vice President – Aircraft & Engines  
[pgibson@aerovi.com](mailto:pgibson@aerovi.com)  
Tel (231) 799-9000  
Cell (231) 215-4977

**PAMELA WILTON**  
Director - Engine Services  
[pw.aesales@aerovi.com](mailto:pw.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 233-1922

**GERARDO MORALES**  
Director Regional, América Latina  
[gmr.sales@aerovi.com](mailto:gmr.sales@aerovi.com)  
Cell 52-1-442-545-7622

**NICK BALDOCK**  
Director of Regional Operations  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
Tel 44 1454 820082  
Cell 44 7773 315567

**RORY GUINA**  
Director – Engine Services  
[Rg.aesales@aerovi.com](mailto:Rg.aesales@aerovi.com)  
Tel (231) 799-9000  
Cell (204) 891-3268