

PW118B ESN AP0048



Visit our website at www.aerovi.com

TSN	30924.40
CSN	41,905
TSO	4.00
CSO	1
TSHSI	4.00

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT / SPT)	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	1	25,000	1.000 / 1.380	18,115
HP Impeller	3072767-01	1	15,000	0.600 / 0.830	18,071
LP Disk	3036412	1	25,000	1.667 / 1.667	14,996
Front Cover	3039640	1	15,000	1.354 / 1.354	11,077
Rear Cover	3039639	1	15,000	1.000 / 1.000	14,999
Inter Stage Seal	3039172	1	15,000	1.000 / 1.000	14,999
HP Disk	3041511	1	15,000	1.000 / 1.000	14,999
PT1 Disk	3038613	1	30,000	1.000 / 1.000	29,999
PT2 Disk	3033914	1	30,000	1.000 / 1.000	29,999
HP Blades	3115601-01	1	15,000	1.000 / 1.000	14,999

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
Vice President
pgibson@erovi.com
Tel (231) 799-9000
Cell (231) 215-4977

PAMELA WILTON
Director Engine Services
pw.aesales@erovi.com
Tel (231) 799-9000
Cell (204) 233-1922

GERARDO MORALES
Regional Director – AL
gmr.sales@erovi.com
Cell 52-1-442-545-7622

NICK BALDOCK
Regional Director – Europe/ Middle
East/ Africa
nbaldock@erovi.com
Tel 44 1454 820082
Cell 44 7773 315567

RORY GUINA
Director Engine Services
Rg.aesales@erovi.com
Tel (231) 799-9000
Cell (204) 891-3268