

PW118B AA0027



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN:	29,581.90
CSN:	42,759
TSO:	0.00
CSO:	0
TSHSI:	0.00

### Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT/SPT)	Cycles Remaining
LP Impeller	3040689	0	25,000	1.000 / 1.380	25,000
HP Impeller	3043294	0	15,000	0.600 / 0.830	15,000
LP Disk	3036412	0	30,000	1.667 / 1.667	30,000
Front Cover	3039640	0	15,000	1.354 / 1.354	15,000
Rear Cover	3039639	0	15,000	1.000 / 1.000	15,000
Inter Stage Seal	3039172	0	15,000	1.000 / 1.000	15,000
HP Disk	3041511	0	15,000	1.000 / 1.000	15,000
PT1 Disk	3038613	0	30,000	1.000 / 1.000	30,000
PT2 Disk	3033914	0	30,000	1.000 / 1.000	30,000
HP Blades	3115601-01	0	15,000	1.000 / 1.000	15,000

**LEGEND:** TSN - Time Since New; CSN - Cycles Since New; TSO - Time Since Overhaul; CSO - Cycles Since Overhaul; TSHSI - Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

**Joel Johnson**  
Senior Director - Program Sales  
[jjohnson@aerovi.com](mailto:jjohnson@aerovi.com)  
(231) 288-7661

**Pamela Wilton**  
Director - Engine Services  
[pw.aesales@aerovi.com](mailto:pw.aesales@aerovi.com)  
(204) 233-1922

**Rory Guina**  
Director - Engine Services  
[rg.aesales@aerovi.com](mailto:rg.aesales@aerovi.com)  
(204) 891-3268

**Rylee Luker**  
Program Coordinator - Engine Sales  
[rluker@aerovi.com](mailto:rluker@aerovi.com)  
(231) 720-0792

**Steve McKee**  
Engine Sales  
[smckee@aerovi.com](mailto:smckee@aerovi.com)  
(231) 327-7886