

PW118B AA0017



Visit our website at www.aerovi.com

TSN:	31,823.20
CSN:	45,515
TSO:	1,167.60
CSO:	1,671
TSHSI:	1,167.60

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT/SPT)	Cycles Remaining
LP Impeller	3040689	1,671	25,000	1.000 / 1.380	16,881
HP Impeller	3072767-01	1,671	15,000	0.600 / 0.830	16,840
LP Disk	3036412	1,671	25,000	1.667 / 1.667	13,326
Front Cover	3039640	1,671	15,000	1.354 / 1.354	9,407
Rear Cover	3039639	1,671	15,000	1.000 / 1.000	13,329
Inter Stage Seal	3039172	1,671	15,000	1.000 / 1.000	13,329
HP Disk	3041511	1,671	15,000	1.000 / 1.000	13,329
PT1 Disk	3038613	8,287	30,000	1.000 / 1.000	21,713
PT2 Disk	3033914	15,542	30,000	1.000 / 1.000	14,458
HP Blades	3115601-01	1,671	15,000	1.000 / 1.000	13,329

LEGEND: TSN - Time Since New; CSN - Cycles Since New; TSO - Time Since Overhaul; CSO - Cycles Since Overhaul; TSHSI - Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

Joel Johnson
Senior Director - Program Sales
jjohnson@aerovi.com
(231) 288-7661

Pamela Wilton
Director - Engine Services
pw.aesales@aerovi.com
(204) 233-1922

Rory Guina
Director - Engine Services
rg.aesales@aerovi.com
(204) 891-3268

Rylee Luker
Program Coordinator - Engine Sales
rluker@aerovi.com
(231) 720-0792

Steve McKee
Engine Sales
smckee@aerovi.com
(231) 327-7886