



Visit our website at www.aerovi.com

PW118 RGB 115577

TSN:	24,762
CSN:	23,977
TSLSV:	-
TSO:	N/A
CSO:	N/A

***RGB is Serviceable with an 8130**

LEGEND: TSN - Time Since New; CSN - Cycles Since New; TSO - Time Since Overhaul; CSO - Cycles Since Overhaul; TSHSI - Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

Joel Johnson
Senior Director - Program Sales
jjohnson@aerovi.com
(231) 288-7661

Rylee Luker
Program Coordinator - Engine Sales
rluker@aerovi.com
(231) 720-0792

Steve McKee
Engine Sales
smckee@aerovi.com
(231) 327-7886