

PW124B 124561



Visit our website at [www.aerovi.com](http://www.aerovi.com)

TSN:	31,085.70
CSN:	30,548
TSO:	0.00
CSO:	0
TSHSI:	0.00

### Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining
HP Impeller	3043293	4,979	15,000	10,021
LP Impeller	3073139-01	4,834	15,000	10,166
HP Disk	3041511	5,225	15,000	9,775
LP Disk	3039512	1,917	15,000	13,083
PT1 Disk	3038513	22,522	30,000	7,478
PT2 Disk	3033914	20,942	30,000	9,058
Interstage Air Seal	3039172	7,627	15,000	7,373
HP Front Cover	3121751-01	3,163	15,000	11,837
HP Rear Cover	3039639	8,044	15,000	6,956
HP Blades	3120973-01	2,098	15,000	12,902

**LEGEND:** TSN - Time Since New; CSN - Cycles Since New; TSO - Time Since Overhaul; CSO - Cycles Since Overhaul; TSHSI - Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

**Joel Johnson**  
Senior Director - Program Sales  
[jjohnson@aerovi.com](mailto:jjohnson@aerovi.com)  
(231) 288-7661

**Rylee Luker**  
Program Coordinator - Engine Sales  
[rluker@aerovi.com](mailto:rluker@aerovi.com)  
(231) 720-0792

**Steve McKee**  
Engine Sales  
[smckee@aerovi.com](mailto:smckee@aerovi.com)  
(231) 327-7886