

PW127M PCE-ED0738			
RGB Module		TMM Module	

TSN:	8,023.30	TSN:	8,023.30
CSN:	6,098	CSN:	6,098
TSO:	N/A	TSO:	N/A
CSO:	N/A	CSO:	N/A
TSHSI:	N/A	TSHSI:	0.00



Visit our website at [www.aerovi.com](http://www.aerovi.com)

### Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining
LP Impeller	3072764-01	6,098	15,000	8,902
HP Impeller	3072766-01	6,098	15,000	8,902
LP Disk	3039412	6,098	15,000	8,902
Front Cover	3039640	0	15,000	15,000
Rear Cover	3039639	6,098	15,000	8,902
Inter Stage Seal	3039172	0	15,000	15,000
HP Disk	3041511	6,098	15,000	8,902
PT1 Disk	3038513	6,098	30,000	23,902
PT2 Disk	3033914	6,098	30,000	23,902
HP Blades	3115601-01	6,098	15,000	8,902

**LEGEND:** TSN - Time Since New; CSN - Cycles Since New; TSO - Time Since Overhaul; CSO - Cycles Since Overhaul; TSHSI - Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

**Joel Johnson**  
Senior Director - Program Sales  
[jjohnson@erovi.com](mailto:jjohnson@erovi.com)  
(231) 288-7661

**Rylee Luker**  
Program Coordinator - Engine Sales  
[rluker@erovi.com](mailto:rluker@erovi.com)  
(231) 720-0792

**Steve McKee**  
Engine Sales  
[smckee@erovi.com](mailto:smckee@erovi.com)  
(231) 327-7886