

PW125B 125029



An LKQ Company

TSN:	31,351
CSN:	32,067
TSO:	5,974
CSO:	5,178
TSHSI:	5,974

LIFE LIMITED PARTS

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor	Cycles Remaining
LP Impeller	3040688	5,175	15,000	1.00	9,825
HP Impeller	3043294	5,175	15,000	0.83	12,897
Front Cover	3039640	12,712	15,000	1.00	2,288
Rear Cover	3039639	5,175	15,000	1.00	9,825
HP Disk	3041511	14,612	15,000	1.00	388
HP Airseal	3039172	5,175	15,000	1.00	9,825
LP Disk	3039512	14,452	15,000	1.00	548
PT1 Disk	3038513	29,286	30,000	1.00	714
PT2 Disk	3033914	5,175	30,000	1.00	24,825
HP Blades	3120983-01	5,175	15,000	1.00	9,825

LEGEND : TSN - Time Since New; CSN - Cycles Since New; TSLSV - Time Since Last Shop Visit; CSLSV - Cycles Since Last Shop Visit

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

Joel Johnson
Director - Engine Sales
jjohnson@aerovi.com
(231) 288-7661

Thomas Otto
Engine Sales
totto@aerovi.com
44 (0) 7714 925293

Rylee Luker
Engine Sales Representative
rluker@aerovi.com
(231) 720-0792

Steve McKee
Engine Sales
smckee@aerovi.com
(231) 327-7886