

PW125B 125145



TSN:	25,656
CSN:	25,375
TSO:	11,269
CSO:	10,526
TSHSI:	2,507

LIFE LIMITED PARTS

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor	Cycles Remaining
LP Impeller	3040688	10,535	15,000	1.00	4,465
HP Impeller	3043294	10,539	15,000	0.83	7,533
Front Cover	3039640	10,530	15,000	1.00	4,470
Rear Cover	3039639	10,530	15,000	1.00	4,470
HP Disk	3041511	10,530	15,000	1.00	4,470
HP Airseal	3039172	10,556	15,000	1.00	4,444
LP Disk	3039512	10,530	15,000	1.00	4,470
PT1 Disk	3038513	25,366	30,000	1.00	4,634
PT2 Disk	3033914	25,366	30,000	1.00	4,634
HP Blades	31115601-01	10,526	15,000	1.00	4,474

LEGEND : TSN - Time Since New; CSN - Cycles Since New; TSLSV - Time Since Last Shop Visit; CSLSV - Cycles Since Last Shop Visit

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

Joel Johnson
Director - Engine Sales
jjohnson@aerovi.com
(231) 288-7661

Thomas Otto
Engine Sales
totto@aerovi.com
44 (0) 7714 925293

Rylee Luker
Engine Sales Representative
rluker@aerovi.com
(231) 720-0792

Steve McKee
Engine Sales
smckee@aerovi.com
(231) 327-7886