

AE3007A1P 312153



An LKQ Company

TSN:	33,762.15
CSN:	26,302
TSLSV:	4.05
CSLSV:	2
LIMIT / LIMITER:	7,565 / 2nd Stg HPT

LIFE LIMITED PARTS

Description	Part Number	Serial Number	Cycles Since New	Cycle Limit	Cycles Remaining
Fan Wheel	23058865	MW70831	6,943	20,000	13,057
Fan Blade Retainer	23062491	HK122636	6,943	20,000	13,057
Fan Drive Shaft	23074382	GV246297	17,565	35,000	17,435
1st Stage Comp Wheel	23084156	L396250	6,943	30,000	23,057
2nd Stage Comp Wheel	23084157	L376734	6,943	30,000	23,057
3rd Stage Comp Wheel	23084158	L376241	6,943	24,200	17,257
4th Stage Comp Wheel	23084159	L374896	6,943	30,000	23,057
5th Stage Comp Wheel	23084160	L380548	6,943	30,000	23,057
6th Stage Comp Wheel	23084161	L374597	6,943	30,000	23,057
7th Stage Comp Wheel	23084162	L363189	6,943	30,000	23,057
8th Stage Comp Wheel	23084163	L373966	6,943	30,000	23,057
9th Stage Comp Wheel	23084164	L358018	12,435	30,000	17,565
10th Stage Comp Wheel	23084165	L412816	2	30,000	29,998
11th Stage Comp Wheel	23084166	L375400	6,943	30,000	23,057
12th Stage Comp Wheel	23084167	L415946	2	30,000	29,998
13th Stage Comp Wheel	23084168	L372626	6,943	30,000	23,057
14th Stage Comp Wheel	23084169	L384960	6,943	30,000	23,057
Comp Shaft Cone Assy	23084170	L378627	6,943	30,000	23,057
1st Stage HPT Wheel	23069591	MM500529	26,302	35,000	8,698
2nd Stage HPT Wheel	23088818	MW64314	12,435	20,000	7,565
1st to 2nd Turb Spacer	23076778	TW517712	17,565	30,000	12,435
1st Stage LPT Wheel	23073957	MW41985	26,302	35,000	8,698
2nd Stage LPT Wheel	23088282	MW44123	26,302	35,000	8,698
3rd Stage LPT Wheel	23079224	MW43109	26,302	35,000	8,698
LPT Int Stg Spacer A	23054049	TW506843	26,302	35,000	8,698
LPT Int Stg Spacer B	23054049	TW506848	26,302	35,000	8,698
LPT Forward Shaft	23074538	GV244452	26,302	35,000	8,698

LEGEND: TSN - Time Since New; CSN - Cycles Since New; TSLSV - Time Since Last Shop Visit; CSLSV - Cycles Since Last Shop Visit

NOTE: SPECIFICATIONS AND/OR DESCRIPTIONS ARE PROVIDED AS INTRODUCTORY INFORMATION ONLY AND DO NOT CONSTITUTE REPRESENTATIONS OR WARRANTIES. ACCORDINGLY, YOU SHOULD RELY ON YOUR OWN INSPECTION OF THESE DOCUMENTS.