

TMM 120424

RGB 121083

TSN	47,011
CSN	45,922
TSO	7,020.1
CSO	7,562
TSHSI	2,432

TSN	42,622.7
CSN	41,634
TSO	5,189.7
CSO	5,830

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining
LP Impeller	3040689	18,198	25,000	6,802
HP Impeller	3043243	7,562	30,000	22,438
LPT Disk	3036212	7,562	30,000	22,438
HPT Front Cover	3049049-01	3,219	15,000	11,781
HPT Rear Cover	3041486	3,219	15,000	11,781
Inter Stage Seal	3041474	3,219	15,000	11,781
HPT Disk	3045591	3,219	15,000	11,781
PT1 Disk	3038613	7,562	30,000	22,438
PT2 Disk	3033914	7,562	30,000	22,438
HPT Blades	3078981-01	3,394	7,500	4,106

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PETE GIBSON
 Vice President
pgibson@erovi.com
 Tel (231) 799-9000
 Cell (231) 215-4977

PAMELA WILTON
 Sales Representative
Pw.aesales@erovi.com
 Tel (231) 799-9000
 Cell (204) 233-1922

NICK BALDOCK
 Regional Director – Europe/ Middle
 East/ Africa
nbaldock@erovi.com
 Tel 011 44 1454 820082
 Cell 011 44 7773 315567

RORY GUINA
 Sales Representative
Rg.aesales@erovi.com
 Tel (231) 799-9000
 Cell (204) 891-3268