

PW127F ESN: 127006



Visit our website at www.aerovi.com

TSN	35,409.50
CSN	37,762
TSO	2,919.40
CSO	3,369
TSHSI	0.00

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3072764-01	3,369	15,000	11,631	11,631
HP Impeller	3072766-01	0	15,000	15,000	15,000
LP Disk	3039412	0	15,000	15,000	15,000
Front Cover	3039640	3,369	15,000	11,631	9,858
Rear Cover	3039639	3,369	15,000	11,631	11,631
Inter Stage Seal	3039172	0	15,000	15,000	12,000
HP Disk	3041511	3,369	15,000	11,631	11,631
PT1 Disk	3038513	18,348	30,000	11,652	11,652
PT2 Disk	3033914	14,172	30,000	15,828	15,828
HP Blades	3115601-01	0	15,000	15,000	15,000

- Fresh hot section inspection and test cell run by StandardAero, March 2017
- LPT, HPT and PT1 blades are all TSN = 0

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

PAMELA WILTON
 Sales Representative
Pw.aesales@erovi.com
 Tel (231) 799-9000
 Cell (204) 233-1922

NICK BALDOCK
 Regional Director – Europe/ Middle
 East/ Africa
nbaldock@erovi.com
 Tel 011 44 1454 820082
 Cell 011 44 7773 315567

RORY GUINA
 Sales Representative
Rg.aesales@erovi.com
 Tel (231) 799-9000
 Cell (204) 891-3268