

PW118B AP0048



An LKQ Company

TSN:	30,924.40
CSN:	41,905
TSO:	4.00
CSO:	1
TSHSI:	4.00

LIFE LIMITED PARTS

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor (RPT/SPT)	Cycles Remaining
LP Impeller	3040689	1	25,000	1.000 / 1.380	18,115
HP Impeller	3072767-01	1	15,000	0.600 / 0.830	18,071
LP Disk	3036412	1	25,000	1.667 / 1.667	14,996
Front Cover	3039640	1	15,000	1.354 / 1.354	11,077
Rear Cover	3039639	1	15,000	1.000 / 1.000	14,999
Inter Stage Seal	3039172	1	15,000	1.000 / 1.000	14,999
HP Disk	3041511	1	15,000	1.000 / 1.000	14,999
PT1 Disk	3038613	1	30,000	1.000 / 1.000	29,999
PT2 Disk	3033914	1	30,000	1.000 / 1.000	29,999
HP Blades	3115601-01	1	15,000	1.000 / 1.000	14,999

LEGEND : TSN - Time Since New; CSN - Cycles Since New; TSLSV - Time Since Last Shop Visit; CSLSV - Cycles Since Last Shop Visit

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

Joel Johnson
Director - Engine Sales
jjohnson@aerovi.com
(231) 288-7661

Thomas Otto
Engine Sales
totto@aerovi.com
44 (0) 7714 925293

Rylee Luker
Engine Sales Representative
rluker@aerovi.com
(231) 720-0792

Steve McKee
Engine Sales
smckee@aerovi.com
(231) 327-7886