

AE3007A1P CAE311126



TSN:	32,751.39
CSN:	27,821
TSLSV:	0.00
CSLSV:	0
LIMIT / LIMITER:	7,179 / Various

LIFE LIMITED PARTS

Description	Part Number	Serial Number	Cycles Since New	Cycle Limit	Cycles Remaining
Fan Wheel	23058865	MW60192	11,228	20,000	8,772
Fan Blade Retainer	23062491	HK121867	11,230	20,000	8,770
Fan Drive Shaft	23065332	GV13709	27,821	35,000	7,179
1st Stage Comp Wheel	23084156	L339041	11,230	30,000	18,770
2nd Stage Comp Wheel	23084157	L330705	11,230	20,000	8,770
3rd Stage Comp Wheel	23084158	L324879	11,230	20,000	8,770
4th Stage Comp Wheel	23084159	L327615	11,230	20,000	8,770
5th Stage Comp Wheel	23084160	L325752	11,230	20,000	8,770
6th Stage Comp Wheel	23084161	L338063	11,230	30,000	18,770
7th Stage Comp Wheel	23084162	L326262	11,230	30,000	18,770
8th Stage Comp Wheel	23084163	L329749	11,230	30,000	18,770
9th Stage Comp Wheel	23084164	L323867	11,230	30,000	18,770
10th Stage Comp Wheel	23084165	L333316	11,230	30,000	18,770
11th Stage Comp Wheel	23084166	L328784	11,230	30,000	18,770
12th Stage Comp Wheel	23084167	L320938	11,230	30,000	18,770
13th Stage Comp Wheel	23084168	L316311	11,230	30,000	18,770
14th Stage Comp Wheel	23084169	L340408	11,230	30,000	18,770
Comp Shaft Cone Assy	23084170	L378452	3,711	30,000	26,289
1st Stage HPT Wheel	23069115	MM120020	26,525	35,000	8,475
2nd Stage HPT Wheel	23088818	MW74091	2,855	23,000	20,145
1st to 2nd Turb Spacer	23076778	TW510963	18,830	30,000	11,170
1st Stage LPT Wheel	23060111	WD89083	27,821	35,000	7,179
2nd Stage LPT Wheel	23058312	WD131454	27,821	35,000	7,179
3rd Stage LPT Wheel	23070046	WD88065	27,821	35,000	7,179
LPT Int Stg Spacer A	23054049	TW14470	27,821	35,000	7,179
LPT Int Stg Spacer B	23054049	TW14786	27,821	35,000	7,179
LPT Forward Shaft	23067076	GV118695	27,821	35,000	7,179

LEGEND: TSN - Time Since New; CSN - Cycles Since New; TSLSV - Time Since Last Shop Visit; CSLSV - Cycles Since Last Shop Visit

NOTE: SPECIFICATIONS AND/OR DESCRIPTIONS ARE PROVIDED AS INTRODUCTORY INFORMATION ONLY AND DO NOT CONSTITUTE REPRESENTATIONS OR WARRANTIES. ACCORDINGLY, YOU SHOULD RELY ON YOUR OWN INSPECTION OF THESE DOCUMENTS.